

- Progress
 - Building structure completed
 - Tower crane removed
 - Exterior façade commenced
 - Interior fit out commenced
- 3 Month Look Ahead
 - Exterior façade
 - Interior fit out

Progress Photographs April 2019 – May 2019









Tower crane removal







Progress Photographs April 2019 – May 2019







